

## Safety Issue Type: Recalls

**September 19 2018**   NHTSA Campaign Number: 18V643000

### Drawbar may Crack and Trailer may Separate

If the trailer separates from the tow vehicle, it can increase the risk of a crash.

**NHTSA Campaign Number**   18V643000

**Manufacturer**   Livin' Lite Recreational Vehicles

**Components**   STRUCTURE

**Potential Number of Units Affected**   154

#### Summary

Livin' Lite Recreational Vehicles (Livin' Lite) is recalling certain 2017-2019 Livin' Lite CampLite travel trailers, models 21BHS, 21RBS, 23RKS and 23RLS. The drawbar of the trailer may crack resulting in the trailer separating from the tow vehicle.

#### Remedy

Livin' Lite will notify owners, and dealers will inspect and repair the welds, as necessary, and install an additional tube to reinforce the drawbar, free of charge. The recall is expected to begin November 5, 2018. Owners may contact Livin' Lite customer service at 1-800-768-4016 extension 154 or 153.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

### Affected Products (3)

#### Vehicle

MAKE	MODEL	YEAR
LIVIN' LITE	CAMPLITE	2017-2019

### Associated Documents (2)

Defect Notice 573 Report

**RCLRPT-18V643-3967.PDF** 216.125KB

<https://static.nhtsa.gov/odi/rcl/2018/RCLRPT-18V643-3967.PDF>

Recall Acknowledgement

**RCAK-18V643-6205.pdf** 247.924KB

<https://static.nhtsa.gov/odi/rcl/2018/RCAK-18V643-6205.pdf>